

Hydraulic Technologies 5885 11th Street Rockford, IL 61109-3699 USA Tech. Services: (800) 477-8326 Fax: (800) 765-8326 Order Entry: (800) 541-1418 Fax: (800) 288-7031

Internet Address: http://www.powerteam.com

Parts List for:


100859 100860 100868

MODEL B
CARTRIDGE STYLE MOUNT

SINGLE-ACTING SWING CLAMP

Capacity: 2400 lbs. Clamping Force (with 2" lg. arm) at 5,000 PSI Max. 100859 - Left Hand, 1/2" Stroke; 100860 - Right Hand, 1/2" Stroke 100868 - Straight Pull, 1/2" Stroke





Issue Date:


2-1-95

Addittional questions can be directed to our Technical Services Department.

Items found in this parts list have been carefully tested and selected. Therefore: Use only genuine Power Team replacement parts!

Refer to any operating instructions included with this product for detailed information about operation, testing, disassembly, reassembly,

and preventive maintenance.



Part	No.		
No.	Req'd	Description	
213836	1	Cap Screw (1/2-20 UNF x 3/4 Lg.; For standard arms. Torque to 45/55 ft. lbs.)	
351025	1	Piston Rod, Roller and Retainer Assembly	
*15892	1	O-ring (1.956 X 1.720 X .118, -924)	
*250620	1	V-ring	
*250621	1	Backup Washer (1-1/4 x 1.014 x .048)	
*210364	1		
*251100	1	Special Washer (Note: Assemble with larger radii towards Backup Washer [Item #6]. Must be grease and oil free.)	
	1	Pin (Assemble with slot towards bottom of clamp.)	
250622	2	Spring Pin (Assemble flush to bottom of End Cap [Item#13] with slots toward center of End Cap.)	
350397	1	Rotating Cam (Left Hand [†] 90° for 100859)	1
350912	1	Rotating Cam (Left Hand [†] 30°)	
350913	1	Rotating Cam (Left Hand [†] 45°)	Grease roller in
350914	1	Rotating Cam (Left Hand [†] 60°)	piston rod (Item
350398	1	Rotating Cam (Right Hand † 90° for 100860)	#2) and cam with
350915	1	Rotating Cam (Right Hand [†] 30°)	a light coating of CDM Extreme
350916	1	Rotating Cam (Right Hand † 45°)	Pressure Lube #3.
350917	1		
350343	1	Rotating Cam (Straight Pull for 100868))
350293	1	End Cap	•
250619	1	Compression Spring (1-1/4 O.D. x 3-1/2 Lg.)	
64337	1	Swing Clamp Body	
*19134	2	Backup Washer (1-3/4 x 1-9/16 c .048, -129)	
*250909	1	O-ring (1-3/4 x 1-9/16 x 3/32, -129)	
*250480	1	V-cup	
*250479	1	Backup Washer (1.113 x 7/8 x .048)	
*250478	1	•	
250618	6	Cap Screw (#6-32 UNC x 1" Lg.; Torque to 30/40 in. lbs.)	
	No. 213836 351025 *15892 *250620 *250621 *210364 *251100 350294 10782 250622 350397 350912 350913 350914 350398 350915 350916 350917 350343 350293 250619 64337 *19134 *250909 *250480 *250479	No. Req'd 213836 1 351025 1 *15892 1 *250620 1 *250621 1 *210364 1 *251100 1 350294 1 10782 1 250622 2 350397 1 350912 1 350913 1 350914 1 350914 1 350398 1 350915 1 350916 1 350917 1 350343 1 350916 1 350917 1 350343 1 350293 1 250619 1 64337 1 *19134 2 *250909 1 *250480 1 *250479 1 *250478 1	No. Req'd Description

Part numbers marked with an asterisk (*) are contained in Repair Kit No. 300611.

[†] Right hand rotation is clockwise rotation when viewed from the piston rod end. Left hand is counterclockwise rotation. To reverse clamp rotation, order the appropriate rotating cam.

