

Hydraulic Technologies  
5885 11th Street  
Rockford, IL 61109-3699 USA

Tech. Services: (800) 477-8326  
Fax: (800) 765-8326  
Order Entry: (800) 541-1418  
Fax: (800) 288-7031

Internet Address:  
<http://www.powerteam.com>

Parts List for:

100901  
100902  
100903

## SINGLE-ACTING SWING / PULL CLAMP

**Max. Capacity: 4,300 lbs. (1952,2 kg) Clamping Force (with 2-1/2" [63,5 mm] lg. arm)  
at 5,000 PSI (350 Bar)**

- 100901 - Left Hand, .600" Stroke**
- 100902 - Right Hand, .600" Stroke**
- 100903 - Straight Pull, .600" Stroke**

The piston rod U-cup seal (Item 13) can be easily twisted if installed incorrectly.


Before installing the piston rod (Item 2) lubricate the rod and all seals with hydraulic oil. Install the rod with light pressure and a twisting motion as the seal is first contacted.

Refer to any operating instructions included with this product for detailed information about operation, testing, disassembly, reassembly, and preventive maintenance.

Items found in this parts list have been carefully tested and selected. Therefore: Use only genuine Hytec replacement parts!

Additional questions can be directed to our Technical Services Department.


Note: Graphics updated at last revision(s) made to this form.



Sheet No. 1 of 1

Rev. 2

Date: 13 Jan. 1999



### **BOTTOM VIEW**

<b>Item No.</b>	<b>Part No.</b>	<b>No. Req'd</b>	<b>Description</b>
1	<b>251630</b>	1	Soc. Hd. Cap Screw (5/8-11 UNC X 1" Lg.; Torque to 50/70 ft. lbs.)
2	<b>351057</b>	1	Piston Rod
3	<b>251738</b>	1	Vented Plug Assembly
4	<b>*251623</b>	1	Vee Block Packing
5	<b>*251625</b>	1	Teflon Backup Washer
6	<b>*251627</b>	1	Teflon Backup Washer
7	<b>*251629</b>	1	Special Steel Washer (NOTE: Assemble washer with larger radii towards teflon washer (Item No. 6); Must be grease and oil free.)
8	<b>11178</b>	1	Slotted Spring Pin (1/4 dia. x 1-1/8 Lg.)
9	<b>350985</b>	1	Rotating Cam (Right Hand† 90° for 100902)
	<b>351045</b>	1	Rotating Cam (Left Hand† 90° for 100901)
	<b>351046</b>	1	Rotating Cam (Straight Pull for 100903)
10	<b>420947</b>	1	End Cap
11	<b>351068</b>	1	Swing Clamp Body
12	<b>251621</b>	1	Compression Spring (1.710 O.D. x 5.250 Lg.)
13	<b>*251624</b>	1	V-cup
14	<b>*251626</b>	1	Teflon Backup Washer
15	<b>*251622</b>	1	Rod Wiper
16	<b>10826</b>	6	Hex Soc. Hd. Cap Screw (8-32 UNC X 1/2 Lg.; Torque to 50-60 in. lbs.)

Part numbers marked with an asterisk (\*) are contained in Repair Kit No. 300818.

† Right hand rotation is clockwise rotation when viewed from the piston rod end.

Left hand is counterclockwise rotation. To reverse clamp rotation,  
order the appropriate rotating cam.