



PRODUCT BULLETIN

Title: Discontinuation of Power Team Protective Blankets
Product Line: Power Team
Document #: PMB1902
Date: April 1, 2019

Product Affected: Power Team Protective Blankets: PB1230C, PB2036C, PB2860C, PB3372C, PB44120C and PB51156C

Distribution: Distributors / Field Sales / Website

Description: Due to a material obsolescence, SPX Flow Hydraulic Technologies can no longer provide its range of Power Team branded protective blankets. The models listed below will be made obsolete. Even though SPX Flow cannot provide a replacement, it is still recommended that some form of safety device (such as a ballistic blanket or protective barrier) be used in applications where broken or flying parts, or potential oil injection, may be present.

Effective Date: The discontinuation of the Power Team protective blankets is effective immediately as existing inventories have already been.

Contact: For questions regarding the obsolescence of the protective blankets, please contact your local sales representative or customer service representative.

Best Regards,

A handwritten signature in black ink that reads "Derek Dreier".

Derek Dreier
Global Product Manager – Hydraulic Technologies
SPX FLOW, Inc.

Products Being Obsoleted:

Discontinued Item
PB1230C
PB2036C
PB2860C
PB3372C

PB44120C
PB51156C