



## PRODUCT BULLETIN

Title: HT50A Hydraulic Tester – No Longer Available  
Product Line: Power Team  
Document #: PMB2001  
Date: June 29, 2020

**Product Affected:** Power Team HT50A

**Distribution:** Distributors / Field Sales / Website

**Description:** Due to component obsolescence, SPX FLOW Hydraulic Technologies can no longer provide the HT50A Hydraulic Tester. The HT75 and HT200, will still be available. Select service components will be available until inventories are depleted.

**Effective Date:** Due to component materials being unavailable, the obsolescence is effective immediately.

**Contact:** For questions regarding the obsolescence of the HT50A, please contact your local sales representative or customer service representative.

### **Products Being Obsoleted:**

Discontinued Item	Description	Suggested Alternate
HT50A	TESTER, HYDRAULIC 50GPM	HT75

Best Regards,

Derek Dreier  
Global Product Manager – Hydraulic Technologies  
SPX FLOW, Inc.